



	TM-50	TM-50 XL	TM-50 OEM	RTM-100	TM 400	TM-500	TM-5100	The Hawk
COMPONENT INPUT								
Manual	X	X	AD	X				
Automatic			AD		X	X	X	X
PICK HEAD TYPE								
Linear					X	X	X	
Rotary								X
INPUT OPTIONS								
Bowl			AD		OP	X	X	X
Tray			AD		OP	X	X	
Tube			AD		OP	X	X	
Tape			AD			X	X	
OUTPUT OPTIONS								
Tray						X	X	
Tube								
Tape	X	X	X	X	X	X	X	X
TAPE WIDTHS	8-72	8-120	8-56	NA	8-72	8-56	8-72	8-24
MAX UPH	AD	AD	AD	AD	3,500	4,500	4,000	22,000
PART MARKING	OP	OP	OP				OP	OP
VISION								
2D	OP	OP	OP		X	OP	OP	OP
3D						OP	OP	
SENSOR PACKAGE	OP	X	X		X		X	X
ROTATION					X	X	X	OP
TESTS	NA	NA	NA		NA	OP	OP	OP

OP = Optional AD = Application Dependent NA = Not Applicable

Note: All Machines accommodate heat activated and pressure sensitive cover tape